

2011-2012 APPRENTICE CLASS SCHEDULE

September 12-16, 2011

Tube Bending/ Crane Person Certification

September 19-23, 2011

❖ Related Math/ Soldering and Brazing

October 10-14, 2011

Drawing Interpretation/ Advanced Drawing

November 7-11, 2011

Pipefitting Manual

November 14 - 17, 2011

❖ Drainage/ Water Supply/ Code

December 5-9, 2011

Intro to HVAC- Section 1&2/or Welding

January 9-13, 2012

Hydronic Heat/ Welding

January, 16-20, 2012

❖ OSHA 30

February 6-10, 2012

Pneumatic Controls/ Welding

March 5-9, 2012

Gas Installation/ Welding

March 12-16, 2012

❖ Pipes, fittings, valves/Pumps/Heritage

April 9-13, 2012

Rigging Certification or Welding

May 7-11, 2012

Foreman Certification or Welding

May 14 – 18, 2012

❖ **Related Sciences/Drawing Interpretation**

EXTRA CREDIT/CORRESPONDENCE CLASSES

You pick up the book at the training center, read and complete all work sheets, or book report, time limited, schedule test at training center, pass test 70% or more, get credit for the class. These classes **are above and beyond** your 4 weeks during the class year. These are not replacement or make-up classes.

- Use and Care of tools – 20 hours credit
 - Gas Tungsten Arc Welding – 20 hours credit
 - Oxy-Fuel Cutting and Welding – 20 hours credit
 - Million Dollar Blue Collar – 20 hours credit
 - Organize or Die – 20 hours credit
 - Survival of the fittest – 20 hours credit
- ✓ Use and Care of tools, Gas Tungsten Arc Welding, and Oxy-Fuel Cutting and Welding will require completed worksheets and pass the review test with 70% or higher.
- ✓ Million Dollar Blue Collar, Organize or Die, Survival of the fittest will require a 500 word book report and pass a written test with 70% or higher. (25 questions)

❖ **Mandatory for apprentices with less than 2500 OJT hours**